

Business Name

**Brookdale Arbor Place** 

## Washington State Patrol Fire Protection Bureau

Phone: (360) 596-3900

Provider Number 2278 Address 12806 Bothell-Everett HWY, Approval Status Disapproved Everett, WA 98208 City, State, Zip Facility Type Residential Care On 06/17/2019 the Office of the State Fire Marshal conducted an inspection at your facility. Code Requirement Statement of Violation 5 Means of egress illumination Illumination shall be provided in the means of egress in During the facility tour on 6/17/2019 it was observed that the accordance with Section 1008.2. Under emergency pwer, facility failed to maintain the emergency egress lighting in the means of egress illumination shall comply with Section 1008.3. building. The finding was: (IFC 1006.1 2015) 1. The egress light in the dinning room failed to illuminate on battery power. 6 Internally illuminated exit signs. Electrically powered, self-luminous and photoluminescent exit During the facility tour on 6/17/2019 it was observed that the signs shall be listed and labeled in accordance with UL 924 facility failed to maintain the illuminated exit signs in the and shall be installed in accordance with the manufacturer's building. The finding was: instructions and Chapter 27 of the International Building Code. Exit signs shall be illuminated at all times. 1. The exit sign on the third floor by the library is not illuminated. (IFC 1013.5 2015) 2. The exit sign in the north stairwell on the first floor is not illuminated.

## Next inspection scheduled on or after:

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

illuminated.

Owner or Authorized Representative

Gary Jacobs, Executive Divector

Deputy State Fire Marshal Don West 2502 112TH ST E

Tacoma WA 98445

(253) 538-3124

Signature

3. The exit sign in the corridor by resident room #107 is not

4. The exit sign in the corridor by the first floor clean

The exit sign in the nurses office is not illuminated.

linen/main laundry is not illuminated.